

Sheet (5)

Synchronous Generator

1) 3-ph, 8 poles, synch. Gen., star connected, the stator has 168 slots with 9 conductors per slot. If rotor speed is 750 rpm find the flux (ϕ) required to generate an emf of 1000 V between lines. Take winding factor = 0.96

(Ans)

$$E_{ph} = 4.44 \cdot f \cdot \phi \cdot N_{ph} \cdot T_w$$

$$E_{ph} = \frac{1000 \text{ V}}{\sqrt{3}}$$

$$T_w = 0.96$$


$$N_s = \frac{120 \cdot f}{P} \quad \therefore f = \frac{N_s \cdot P}{120} = \frac{750 \times 8}{120} = 50 \text{ Hz}$$

$$\text{total no. of conductors} = 168 \times 9 = 1512 \text{ conductors}$$

$$N_{ph} = \frac{2 \times \text{no. of conductors}}{2} = 3024 \text{ turns}$$

$$\phi = \frac{1000/\sqrt{3}}{4.44 \times 50 \times 0.96 \times (3024)}$$

$$\phi = 8.958 \times 10^{-4} \text{ Wb}$$



2 conductors = 1

$$N = 1$$

$$D = 7$$


$$Z = 11$$

$$A = 10$$

$$\frac{Z}{P} = 2$$

In a 50 KVA, star connected, 440V, 3ph, 50 Hz alternator. The $R_a = 0.25 \Omega/\text{phase}$, $X_a = 3.7 \Omega/\text{phase}$. at Rated load find:

- ① emf/phase
- ② voltage regulation
- ③ sketch phasor diagram.



$$E_a = V_{ph} + I_a(R_a + jX_a)$$

$$S_L = 50 \text{ KVA}$$

$$S_L = \sqrt{3} V_L I_a$$

$$\therefore I_a = \frac{S_L}{\sqrt{3} \cdot V_L} = \frac{50 \times 10^3}{\sqrt{3} \times 440} = 65.6 \text{ A}$$

at unity P.f means V_{ph} is in phase with I_a

$$\cos^{-1}(1) = 0$$


$$\therefore I_a = 65.6 \angle 0^\circ \text{ A}$$

$$E_a = \frac{440}{\sqrt{3}} + 65.6 \angle 0^\circ (0.25 + j3.7) = 363.4 \angle 42^\circ$$

$$\text{VR\%} = \frac{V_{NL} - V_{FL}}{V_{FL}} \times 100 = \frac{|E_a| - |V_{ph}|}{|V_{ph}|} \times 100$$

$$= \frac{363.4 - \frac{440}{\sqrt{3}}}{\frac{440}{\sqrt{3}}} \times 100 = 43.05\%$$

phasor diagram at unity P.f.



Sheet (5) بالترتيب

[3] $P_{out} = 5 \text{ Kw}$, $V_L = 110 \text{ V}$, $I_a = 29 \text{ A}$ lag P-f , $f = 50 \text{ Hz}$
 $N_s = 1000 \text{ rpm}$, $R_a = 0.1 \Omega/\text{ph}$, $X_s = 1.53 \Omega/\text{ph}$

$I_f \Rightarrow I_{f1}$ at full load
 field current

[9] Req: ① E_{aBph} ② VR% ③ no. of poles (p)

$\therefore N_s = \frac{120f}{p} \quad \therefore p = \frac{120f}{N_s} = \frac{120 \times 50}{1000} = \boxed{6 \text{ poles}}$

$\Rightarrow E_{aBph} = V_{ph} + I_a (R_a + jX_s)$

$\therefore P_{out} = 5 \times 10^3 = \sqrt{3} V_L I_a \cos \phi$

$\therefore \cos \phi = \frac{5 \times 10^3}{\sqrt{3} \times 110 \times 29} = 0.905$

$\Rightarrow I_a = 29 \angle -\cos^{-1}(0.905) = 29 \angle -25.1^\circ$

$\therefore E_{aBph} = \frac{110}{\sqrt{3}} + (29 \angle -25.1^\circ) \times (0.1 + j1.53) = \boxed{93.5 \angle 24.6^\circ \text{ V}}$

$\therefore \text{VR\%} = \frac{E_{aBph} - V_{ph}}{V_{ph}} \times 100 = \frac{93.5 - \frac{110}{\sqrt{3}}}{\frac{110}{\sqrt{3}}} = \boxed{47.22\%}$

[b] if field current is reduced to 0.9 I_{f1} while speed is constant
 find the load voltage if supply the same load at the same P-f? ($V_{ph} = ?$)

$\therefore I_{f2} = 0.9 I_{f1} \quad \therefore E_{ph2} = 0.9 E_{ph}$

$\therefore I_{a2} = 29 \angle -25.1^\circ \text{ A}$

بالترتيب

(3)

$$\therefore E_{ph} = V_{ph} + I_a (R_a + jX_s)$$

$$\therefore V_{ph2} = E_{ph2} - I_a (R_a + jX_s)$$

مقدار
التيار

$$\boxed{I_a \cos \phi = \text{Constant}}$$

$$\boxed{E_{ph} \sin \delta = \text{Constant}}$$

هو قائل
النظام
P.F. 0.8

$$\therefore E_{ph} \sin \delta = E_{ph2} \sin \delta_2$$

$$E_{ph} \sin \delta = 0.9 E_{ph} \sin \delta_2$$

$$\therefore \sin (24.63) = 0.9 \times \sin \delta_2$$

$$\therefore \delta_2 = 27.5^\circ$$

$$\therefore V_{ph2} = 0.9 \times 93.5 \angle 27.5^\circ - (291 \angle 25.1^\circ + (0.1 + j1.53))$$

$$\therefore V_{ph2} =$$

[c] If the speed, field current & load current are kept constant the P.F. changed to 0.8 lead, $V_{ph3} = ?$

مقدار $E_{ph3} = E_{ph}$, $I_{f3} = I_f$, $N = \text{Const}$

$$\therefore I_{a3} = 291 \angle \cos^{-1}(0.8) = 291 \angle 36.87^\circ$$

$$\therefore V_{ph3} = E_{ph3} - I_{a3} (R_a + jX_s)$$

$$V_{ph3} = 93.5 \angle 83^\circ - (291 \angle 36.87^\circ) \times (0.1 + j1.53)$$

$$\therefore V_{ph3} + j \times (0) = 93.5 \cos 83^\circ + j 93.5 \sin 83^\circ + 24.3 + j 37.36$$

بمسألة ال Real مع ال Real والتخيل مع التخيل

$$\therefore j \times (0) = 0 = 93.5 \sin 83^\circ + 37.36$$

$$\therefore \boxed{83 = 23.4^\circ}$$

$$\therefore V_{ph3} = 93.5 \angle 23.4^\circ + 291 \angle 36.87^\circ (0.1 + j1.53) = \checkmark$$

(4)

1) $P = 6$ poles, 3ph, star, $P_{out} = 100 \text{ kW}$, $P.f. = 0.8$ lead
 $f = 60 \text{ Hz}$, $V_L = 2 \text{ kV}$, $R_a = 0.4 \Omega/\text{ph}$, $X_s = 4 \Omega/\text{ph}$
 find ① VR%. ② max. developed power ③ $\eta\%$ if $P_g = 100 \text{ kW}$

$$\therefore V_{ph} = \frac{2 \times 10^3}{\sqrt{3}} \text{ V}$$

المسألة

Prot.
مفاد
دورانية

$$E_{ph} = V_{ph} + I_a (R_a + jX_s)$$

$$\therefore P_{out} = \sqrt{3} V_L I_a \cos \phi$$

$$\therefore I_a = \frac{100 \times 10^3}{\sqrt{3} \times 2 \times 10^3 \times 0.8} = 36.1$$

$$\therefore I_a = 36.1 \angle 36.87^\circ \text{ A}$$

$$\therefore E_{ph} = \frac{2 \times 10^3}{\sqrt{3}} \text{ V} + (36.1 \angle 36.87^\circ) \times (0.4 + j4)$$

$$\therefore E_{ph} = 1086.7 \angle 6.6^\circ \text{ V}$$

$$\text{VR}\% = \frac{E_{ph} - V_{ph}}{V_{ph}} \times 100 = \frac{1086.7 - \frac{2000}{\sqrt{3}}}{\frac{2000}{\sqrt{3}}}$$

$$\therefore \text{VR}\% = -5.88\%$$

المفاد
Lead
و يطلع موجب
Lead

المفاد

$$P_{max} = \frac{V_{ph} \times E_{ph}}{X_s}$$

$$\therefore P_{max} = \frac{\frac{2000}{\sqrt{3}} \times 1086.7}{4} = 341 \text{ kW}$$

$$\eta\% = \frac{P_{out}}{P_{in}} = \frac{P_{out}}{P_{out} + P_{losses}} = 89\%$$

⑤
 $P_{copper} = 3 I_a^2 R_a$
 $= 3 (36.1)^2 \times 0.4$
 $P_{fri} \text{ or } P_{rot.} \rightarrow 10 \times 10^3 \text{ W}$

$S = 40 \text{ KVA}$, 380 V , 4 pole, 50 Hz , star connected spn
 $R_a = 0.04 \Omega/\text{ph}$, $X_s = 0.42 \Omega/\text{ph}$, $T_{ph} = 100 \text{ turns/ph}$
 Find: ① E_{ph} at full load with 0.8 lag P.f , $V\%$.
 ② N_s
 ③ ϕ

- JSI -

$$V_{ph} = \frac{380}{\sqrt{3}} = 220 \angle 0^\circ \text{ V}$$

$$I_a = \frac{S}{\sqrt{3} V_L} = \frac{40 \times 10^3}{\sqrt{3} \times 380} = 60.77 \angle -36.87^\circ \text{ A}$$

$$\therefore E_{ph} = V_{ph} + I_a (R_a + jX_s) = \frac{220}{\sqrt{3}} \angle 0^\circ + (60.77 \angle -36.87^\circ)(0.04 + j0.42)$$

$$\therefore E_{ph} = 237.2 \angle 4.35^\circ \text{ V}$$

$$V\% = \frac{E_{ph} - V_{ph}}{V_{ph}} \times 100 = \frac{237.2 - 220}{220} = 37.82\%$$

$$N_s = \frac{120 f}{p} = \frac{120 \times 50}{4} = 1500 \text{ rpm}$$

$$\phi \rightarrow \therefore E_{ph} = 4.44 \phi f T_{ph} (Kw) \rightarrow \begin{matrix} \text{Kw} = \text{weber} \\ 1 = \text{weber} \end{matrix}$$

$$\therefore \phi = \frac{E_{ph}}{4.44 f T_{ph}} = \frac{237.2}{4.44 \times 50 \times 100}$$

$$\therefore \phi = 0.0107 \text{ Wb} \rightarrow \text{weber}$$